



报告编号: HYI260814HA9106

第 1 页 共 4 页

检 测 报 告

Test Report

送检企业: 安平县明尚交通设施工程有限公司

样品名称: 交通标志杆

检验类别: 委托检验

厦门泓益检测有限公司

Xiamen Hongyi Testing Technology Co.Ltd

检测专用章

This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Hongyi Testing, this test report shall not be copied except in full and published as advertisement Hongyi Physical & Chemical Lab.

厦门泓益检测有限公司
Xiamen Hongyi Testing Co., Ltd.

地址: 福建省厦门市同安区轻工食品工业美禾路 99 号

ADDRESS: No. 99 Meihe Road, Light Industry Food Industrial Zone, Tongan District, Xiamen City, Fujian Province,

邮箱: hongyotest@123.com 网址: <https://www.hongyi-lab.com/>



报告编号: HYI260814HA9106

样品名称	:	交通标志杆	型号规格	:	/
商标	:	/	样品数量	:	1 套
委托单位	:	安平县明尚交通设施工程有限公司			
委托单位地址	:	安平县高新区经六路与纬三路交叉口东行 800 米路南			
生产单位	:	安平县明尚交通设施工程有限公司			
生产单位地址	:	安平县高新区经六路与纬三路交叉口东行 800 米路南			
检验类别	:	委托检验	测试日期	:	2026 年 08 月 07 日至 2026 年 08 月 14 日
签发日期	:	2026 年 08 月 14 日			
检验依据	:	GB/T 700-2006 碳素结构钢 GB/T 1839-2025 钢产品镀锌层质量试验方法			
检验项目	:	见后续			
样品特征和状态	:	完好			
环境温度	:	24.6℃	环境湿度	:	51.8%
测试结果	:	本次委托检验, 所检项目全部符合标准要求			

报告编制: 张华伟

报告审核: 杨泽群



This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Hongyi Testing, this test report shall not be copied except in full and published as advertisement Hongyi Physical & Chemical Lab.

厦门泓益检测有限公司
Xiamen Hongyi Testing Co., Ltd.

地址: 福建省厦门市同安区轻工食品工业区美禾路 99 号

ADDRESS: No. 99 Meihe Road, Light Industry Food Industrial Zone, Tongan District, Xiamen City, Fujian Province,

邮箱: hongyotest@123.com 网址: https://www.hongyi-lab.com/



检测项目		单位	标准要求	测试结果	判定
无缝钢管立柱		mm	$\phi 114 \times 5.5 \times 4500$	符合要求	合格
柱帽		mm	$\phi 114 \times 4.5$	符合要求	合格
底座加劲肋		mm	$200 \times 120 \times 50 \times 30$	符合要求	合格
封顶钢板		mm	$\phi 114 \times 5.5$	符合要求	合格
Q235B 化学成分	C	%	≤ 0.20	0.19	合格
	Si	%	≤ 0.35	0.28	合格
	Mn	%	≤ 1.40	1.35	合格
	P	%	≤ 0.045	0.033	合格
	S	%	≤ 0.045	0.040	合格
镀锌量		g/m^2	≥ 600	601	合格

以下空白

This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Hongyi Testing, this test report shall not be copied except in full and published as advertisement Hongyi Physical & Chemical Lab.

厦门泓益检测有限公司
Xiamen Hongyi Testing Co., Ltd.

地址: 福建省厦门市同安区轻工食品工业区美禾路 99 号

ADDRESS: No. 99 Meihe Road, Light Industry Food Industrial Zone, Tongan District, Xiamen City, Fujian Province,

邮箱: hongyotest@123.com 网址: <https://www.hongyi-lab.com/>

测
专用



报告编号: HYI260814HA9106

注 意 事 项:

1. 报告无“检验报告章”或检验单位公章无效。
2. 未经本实验室书面同意,不得部分复制本报告。
3. 报告无主检、审核、批准人签字无效。
4. 报告涂改无效。
5. 对检测报告若有异议,应于收到报告之日起十五日内向检测单位提出,逾期不予受理。
6. 委托检测仅对来样负责。

地址: 福建省厦门市同安区轻工食品工业区美禾路 99 号

Add: No. 99 Meihe Road, Light Industry Food Industrial Zone, Tongan District, Xiamen City, Fujian Province,

报告结束

This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Hongyi Testing, this test report shall not be copied except in full and published as advertisement Hongyi Physical & Chemical Lab.

厦门泓益检测有限公司
Xiamen Hongyi Testing Co., Ltd.

地址: 福建省厦门市同安区轻工食品工业区美禾路 99 号

ADDRESS: No. 99 Meihe Road, Light Industry Food Industrial Zone, Tongan District, Xiamen City, Fujian Province,

邮箱: hongyotest@123.com 网址: <https://www.hongyi-lab.com/>

有限公司
章